



Wymiar nominalny DN/ α	Bosy koniec		Kielich	
	D	L2	D	L1
32 / <math>< 15^\circ</math>	32 ^{+0,3} / _{+0,0}	46,0	32 ^{+0,6} / _{+0,3}	37,0
32 / <math>< 30^\circ</math>	32 ^{+0,3} / _{+0,0}	46,0	32 ^{+0,6} / _{+0,3}	36,5
32 / <math>< 45^\circ</math>	32 ^{+0,3} / _{+0,0}	46,0	32 ^{+0,6} / _{+0,3}	36,5
32 / <math>< 67,5^\circ</math>	32 ^{+0,3} / _{+0,0}	46,0	32 ^{+0,6} / _{+0,3}	36,5
32 / <math>< 87,5^\circ</math>	32 ^{+0,3} / _{+0,0}	46,0	32 ^{+0,6} / _{+0,3}	36,0
40 / <math>< 15^\circ</math>	40 ^{+0,3} / _{+0,0}	49,0	40 ^{+0,7} / _{+0,3}	45,0
40 / <math>< 30^\circ</math>	40 ^{+0,3} / _{+0,0}	49,0	40 ^{+0,7} / _{+0,3}	45,0
40 / <math>< 45^\circ</math>	40 ^{+0,3} / _{+0,0}	49,0	40 ^{+0,7} / _{+0,3}	45,0
40 / <math>< 67,5^\circ</math>	40 ^{+0,3} / _{+0,0}	49,0	40 ^{+0,7} / _{+0,3}	45,0
40 / <math>< 87,5^\circ</math>	40 ^{+0,3} / _{+0,0}	49,0	40 ^{+0,7} / _{+0,3}	45,0
50 / <math>< 15^\circ</math>	50 ^{+0,3} / _{+0,0}	48,0	50 ^{+0,7} / _{+0,3}	45,0
50 / <math>< 30^\circ</math>	50 ^{+0,3} / _{+0,0}	48,0	50 ^{+0,7} / _{+0,3}	45,0
50 / <math>< 45^\circ</math>	50 ^{+0,3} / _{+0,0}	47,0	50 ^{+0,7} / _{+0,3}	44,5
50 / <math>< 67,5^\circ</math>	50 ^{+0,3} / _{+0,0}	48,0	50 ^{+0,7} / _{+0,3}	44,0
50 / <math>< 87,5^\circ</math>	50 ^{+0,3} / _{+0,0}	49,0	50 ^{+0,7} / _{+0,3}	44,0
75 / <math>< 15^\circ</math>	75 ^{+0,4} / _{+0,0}	60,0	75 ^{+0,9} / _{+0,4}	51,0
75 / <math>< 30^\circ</math>	75 ^{+0,4} / _{+0,0}	60,0	75 ^{+0,9} / _{+0,4}	51,0
75 / <math>< 45^\circ</math>	75 ^{+0,4} / _{+0,0}	60,0	75 ^{+0,9} / _{+0,4}	51,0
75 / <math>< 67,5^\circ</math>	75 ^{+0,4} / _{+0,0}	59,0	75 ^{+0,9} / _{+0,4}	51,0
75 / <math>< 87,5^\circ</math>	75 ^{+0,4} / _{+0,0}	59,0	75 ^{+0,9} / _{+0,4}	50,5
110 / <math>< 15^\circ</math>	110 ^{+0,4} / _{+0,0}	64,0	110 ^{+0,9} / _{+0,4}	56,0