



J&J India Sourcing LLP

Specification Sheet- Hand Tools

Front View	Back View	Arrangement
------------	-----------	-------------

4. Onsite Test Requirements

Hardness <input checked="" type="checkbox"/>	Torque <input checked="" type="checkbox"/>	Go – NoGo Gauge <input checked="" type="checkbox"/>
--	--	---

5. Item details & Logistic data

Buyer ref#	Vendor ref#	Size (mm)	J&J Seal #	Unit Pack			Inner Pack				Master Pack			
				Barcode	Dimensions In cms Tol.+/-3%	Wt. (Kg) Tol.+/-5%	Barcode	Dimensions In cms Tol.+/-3%	Wt. (Kg) Tol.+/-5%	Qty	Barcode	Dimensions In cms Tol.+/-3%	Wt. (Kg) Tol.+/-5%	Qty
17-DEXTER	COMB. 6DEXTER	6		3276007119190	11X5 X.7	.025	12X5X2.5	.085	3		42X26X27	14.600 KG	480	

6. Quality Plan

Approvals / Inspections Required	Initial POs	Repeat POs	Approvals / Inspections Required	Initial POs	Repeat POs
1. Approval of labels, tags and shipping mark	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	5. Midline inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Approval of production sample	<input checked="" type="checkbox"/>	<input type="checkbox"/>	6. Pre-shipment inspection	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3. Product testing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	7. Container loading inspection	<input type="checkbox"/>	<input type="checkbox"/>
4. Inline inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>

7. Sampling Plan for Pre-shipment Inspection

Inspection Level for Inspections	G1	Sampling Plan	Normal	AQL	Critical	Major	Minor
Inspection Level for Testing	S1				0	2.5	4.0

8. Labeling / Packaging Instructions

Step 1	Step 2	Step 3
Step 4	Step 5	Step 6



Specification Sheet- Hand Tools

Step 7	Step 8	Step 9

9. Quality Check Points

- Visual Check
- GO/NO GO Gauge Check
- Hardness Test
- Torque Test
- Marking/label/barcode check.
-
-
-

		Date of Issue	
Merchant	QA Inspector	Rev #	00